




Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
OLD HAY CLOSE	O/S 34	Dangerous	Stem wounded at crown break, poor structural condition	Prunus Kanzan	Plant centrally in verge o/s 34 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
OLD HAY CLOSE	O/S 9 (opp 36)	Damaging	F/W uplifted by shallow rooting	Prunus Kanzan	Plant in verge o/s 9 (opposite 36, same position as felled tree)	Crataegus 'Pauls Scarlett'
OLD HAY CLOSE	O/S 17	Damaging	Kerbs displaced and f/w mounded/recently patch repaired	Prunus Kanzan	Plant centrally in verge o/s 36 (same position as felled tree)	Crataegus 'Pauls Scarlett'
OLD HAY CLOSE	O/S 33	Damaging	F/W mounded/damaged and stem cankered	Prunus Kanzan	Plant centrally in verge o/s 33 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
OLD HAY CLOSE	O/S 76	Dangerous	Stem decayed, poor structural condition	Malus sp	Plant centrally in verge o/s 76 (same position as felled tree)	Not Known
OLD HAY CLOSE	O/S 78	Damaging	F/W mounded, recently patch repaired	Malus sp	Plant centrally in verge o/s 78 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
OLD HAY CLOSE	O/S 26	Damaging	F/W uplifted/mounded by shallow roots	Prunus Kanzan	Plant centrally in verge o/s 26 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
OLD HAY CLOSE	O/S 1	Dangerous	Weak union at crown break, swelling VTA symptom	Prunus Kanzan	Plant centrally in verge o/s 1 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
OLD HAY CLOSE	Side of 3 Old Hay Lane, ON Old Hay Close	Dangerous	Multiple weak union at crown break, structural integrity in doubt	Prunus Kanzan	Plant centrally in verge o/s 2 (same position as felled tree)	Crataegus 'Pauls Scarlett'
OLD HAY CLOSE	O/S 30	Damaging	Rooting through kerbstones into c/w, f/w damage also	Prunus Kanzan	plant in verge centrally o/s 30, (same as felled tree)	Malus 'Rudolph'
OLD HAY CLOSE	O/S 11	Dangerous	Significant scaffold dieback, poor physiological condition, <2yrs expected lifespan	Prunus Kanzan	Plant centrally in verge o/s 11 (same as felled tree)	Malus 'Rudolph'
OLD HAY CLOSE	O/S 74	Dead	dead	Prunus Kanzan	plant in verge centrall o/s 74, (same as old tree)	Malus 'Rudolph'